

## **ELASTOMERS**

### **EPDM**

Good resistance to Inorganic and Organic Dilute Acids and Lyes up to 80 Degree C, Abrasion and Ageing. Good resistance to Hot Water and Steam up to 130 Degree C. Not resistant to Animal, Vegetable or Mineral Oils. Continuous operating temperature: - 40 Degree C to + 130 Degree C.

### **SILICONE**

Good resistance to Weak Acids and Lyes up to 80 Degree C. Good resistance to Hot Water and Steam up to 130 Degree C. Not resistant to Hydrocarbons or Mineral Oils. Continuous operating temperature: -40 Degree C to + 130 Degree C.

### **VITON**

Good resistance to Animal, Vegetable and Mineral Oils. Not resistant to Solvents or Superheated Water Vapour. Continuous operating temperature: -15 Degree C to + 220 Degree C.